

Dark Fiber Inquiry Form

Inquiry Number: CTCCNHDOVRMNCH12-5-1SD CLEC Section (E-mail form to une.dfi@verizzon.com **CLEC Name** CTC Communications Corp Date Sent 12/5/01 CLEC Contact Randy Schmid Tel Number 781-522-8739 Street 220 Bear Hill Road Fax Number 781-522-8798 Floor/Room City & State Waltham, MA 02451 E-Mail Rschmid@ctcNet.com **Location Information Section** Verizon Central Office Primary Location POICLLI DOVRNHTH Street 57 Saint Thomas Street Dover, New Hampshire City & State LATA 122 Additional Information Secondary Location Verizon Central Office XPOI CLLI MNCHNHCO Street 25 Concord Street City & State NPA-NXX 603-518 Manchester, New Hampshire Additional Information 2 Number Of Fiber Pairs Required (Each Pair Equals 2 Strands) Service Delivery Engineer (SDE) Information Section Date Forward to Engineering 12/5/01 Date Received 12/5/01 SDE Tel Number 617-743-1936 Sean Duggan Street 125 High St., Rm 1256 FAX Number 617-261-6461 Boston, MA 02110 City & State E-Mail Sean.m.duggan@verizon.com Date Reply To CLEC **Engineering Information Section** Date Received 12/8/01 Reply To SDEE By 12/27/01 Engineer Harv Tasch Reply Doate 12/19/01 240 East 38th Street Tel Numbber 212-338-8698 Street New York, NY, 10016 FAX Numbber 212-370-2050 City & State **IOF Planning** E-MMail Organization Harvey. Tasch@Verizon.com NO DIRECT ROUTE: DOVRNHTH-BNTONHPR-NWWDDNHYA-EDSMNHBH-CNCRNHSO-Comments MNCHNHCO NO SPARE FIBERS AVAILABLE ## Fibers Available To Meet Request (Y/N) Ν If NO, Number Of Fiber Pairs tivity

NOTICE: This does not constitute an order for Dark Fiber. Tito order available Dark Fiber, the CLEC must follow-up with an ASF delivered to Verizon as soon as possible following notificatition of availability. Until an ASR is received by Verizon, Dark Fibe remains in inventory and available for Verizon use and/or to morest other CLEC requests. Verizon does not reserve Dark Fiber.

Information contained in this response is based solely upon a a review of Verizon's cable records. Verizon makes no representation or warranty regarding the accuracy or completeness of such a records. The CLEC has the option of requesting Verizon perform field survey at the CLEC's expense to verify Dark Fiber availability. Should the CLEC decline the field survey and place an order to Dark Fiber based solely on the information contained in this reresponse, the CLEC assumes all risks of relying on such records.



To: rschmid@CTCNet.com

CC:

Subject: Dover to Manchester NH Cable documentation

Randy,

As discussed here is the documentation for the NH inquiry.

(See attached file: dover-manchester.ppt)(See attached file Dove-Manchester fiber route.doc)(See attached file: CTCCNHDOVRMNCH12-5-1SD.doc)

CICCIAIDOVICIACIAED S IDD. COO,
Please call with any questions/concerns and I'll try to clarify
Thanks,
Sean
- dover-manchester.ppt
- Dove-Manchester fiber route.doc
- CTCCNHDOVRMNCH12-5-1SD.doc

The legend for the ASGT ACTIVITY columns area

Working & in-effect

W

```
$
    Spare
Ī
    Jumpered fiber is open, defective, or reserved for pending seservice requirement
COMMAND
                CABLE BULK ASSIGNMENT ANND SCAN (CBLS) /FOR
TERM A DOVRNHTH
                    TERM Z BNTONHPR
                                        CAABLE 7760
                                                       SUBPATH CT0001
FROM UNIT 00001
                 LAST UNIT 00012 QTY SPARRE 0000
                                                    TOT OTY 0012
CMPL DATE 12 16 91 INV STAT IE
                                2-W SPARESS 0000 1-W SPARES 0000
FAC DETAIL LGS
                   FAC USE G FAC GROUP
                                               COMP ID
NO OF SPRS
             NO OF WIRES
                           SHLD/DIR
                                        CKKT/CLO SCAN N
ASGT DATA: ALT/PRI
                     DR CLASS
                                MISUSE
                                        MW
            TERMN: FRAMES
                               SEQ NBR
  SUBD ASGT ACTIVITY
                                                  DUE DATE
UNIT FTRSTNCUR PNDDF
                               CKTID/CLO
        W W Y C 301 /T6X2P/CNCRNHSO /MNCCHNHCO
100001
                                                       030293
00002
        W W Y C 301 /T6X2P /CNCRNHSO /MNCCHNHCO
                                                       030293
        W WYC301 /T6X2P/DOVRNHTH /MNGCHNHCO
                                                       02249
00003
        W W Y C 301 /T6X2P/DOVRNHTH /MNUCHNHCO
                                                       02249
00004
00005
        W WYC305 /T3X2P/DOVRNHTH /ROCCHNHWE
                                                       12069:
        W W Y C 305 /T3X2P /DOVRNHTH /ROCCHNHWE
                                                       12069:
00006
00007
        W W C 1001 /OC12 /BNTONHPR /DOVRRNHTH
                                                      031196
        W W C 1001 /OC12 /BNTONHPR /DOVRRNHTH
80000
                                                      031196
        W W C 1001 /OC12 /DOVRNHTH /NWODDNHYA
00009
                                                       112197
        W W C 1001 /OC12 /DOVRNHTH /NWODDNHYA
01000
                                                       112197
        W W S 83/LXFU/150020 /NE
00011
                                             02129
        W W S 83/LXFU/150020 /NE
00012
                                             02129
        W W C 1001 /OC48 /CNCRNHSO /DOVRRNHTH
                                                     021497
00013
00014
        W W C 1001 /OC48 /CNCRNHSO /DOVRRNHTH
                                                     021497
        W W C 1001A/OC48 /DOVRNHTH /ROCCHNHWE
                                                      081999
00015
00016
        W W C 1001A/OC48 /DOVRNHTH /ROCCHNHWE
                                                      081999
        W W C 1002 /OC12 /DOVRNHTH /NWODDNHYA
                                                      020100
00017
00018
        W W C 1002 /OC12 /DOVRNHTH /NWODDNHYA
                                                      020100
              PENDING DWDMNH01
00019
        JJ
00020
              PENDING DWDMNH01
        JJ
00021
        $ $
00022
        JJ
               MTCE SPARE
00023
        JJ
              MTCE SPARE
00024
        JJ
              PENDING NHNOKN
00025
        JJ
              PENDING NHNOKN
        W W C 3002 /OC48 /CNCRNHSO /DOVRRNHTH
                                                     020400
00026
        W W C 3002 /OC48 /CNCRNHSO /DOVRRNHTH
                                                     020400
00027
         W W C 101 /OMC /CNCRNHSO /DOVRRNHTH
                                                     020501
00028
         W W C 101 /OMC /CNCRNHSO /DOVRRNHTH
                                                     020501
00029
00030
        JJ
               MAINTENANCE SPARE
00031
        JJ
               MAINTENANCE SPARE
00032
        $ $
00033
        $ $
00034
        $ $
      JMP J J OPEN FIBER
00037
     JMP J J OPEN FIBER
00038
00039
        W W S 74/LMDA/72578
                                             021296
00040
         W W S 74/LMDA/72578
                                             021296
```

CABLE BULK ASSIGNMENT AND SCAN (CBLS) /FOR COMMAND TERM A BNTONHPR TERM Z NWODNHYA CABLE 7639 SUBPATH CT000F FROM UNIT 00001 LAST UNIT 00012 OTY SPARE 0000 TOT OTY 0012 CMPL DATE 12 31 91 INV STAT IE 2-W SPARES 0000 1-W SPARES 0000 FAC USE G FAC GROUP FAC DETAIL LGS COMP ID NO OF SPRS NO OF WIRES SHLD/DIR CKT/CLO SCAN N

ASGT DATA: ALT/PRI DR CLASS MISUSE MMW TERMN: FRAMES SEQ NBR

SUBD ASGT ACTIVITY

	א זספע עם				
UNIT		CUR PND D F			DUE DATE
00001				/MNCCHNHC	
00002	w w	Y C 301 /T6X2	P/CNCRNHSO	/MNCCHNHC	030293
00003	w w	Y C 301 /T6X2	P /DOVRNHTH	MNCCHNHC	022493
00004	$\mathbf{w} \mathbf{w}$	Y C 301 /T6X2	P/DOVRNHTH	MNOCHNHC	022493
00005	w w	C 1001/OC12	/DOVRNHTH	/NWODDNHY/	112197
00006	w w	C 1001/OC12	/DOVRNHTH	/NWODDNHY/	112197
00007	J J	PENDING_DV	VDMNH01		
00008	JЈ	PENDING_DV	VDMNH01		
00009	JJI	MTCE SPARE			
00010	JJI	MTCE SPARE			
00011	DEF J J	DEFECTIVE		0012601	
00012	w w			/ROCCHNHW	E 090999
00013	w w	C 1001 /OC48	/CNCRNHSO	/DOVRRNHTH	021497
00014	w w		/CNCRNHSO	· · · -	021497
00015	w w			/NWODDNHYA	
00016	$\mathbf{w} \ \mathbf{w}$			NWODDNHYA	061299
00017	$\mathbf{w} \ \mathbf{w}$			/ROCHINHWE	
00018	$\mathbf{w} \ \mathbf{w}$		/CNCRNHSO	/ROCHINHWE	
00019	$\mathbf{w} \mathbf{w}$			/ROCCHNHW	
00020			/DOVRNHTH		
00021	$\mathbf{w} \ \mathbf{w}$		/DOVRNHTH		
00022			/CNCRNHSO	/DOVERNHTH	
00023	w w		/CNCRNHSO	/DOVRRNHTH	020400
00024		MTCE SPARE			
00025	D EF J	DEFECTIVE		0080100	
00026	DEF J J	DEFECTIVE		0080100	
00027	DEF J J	DEFECTIVE	-	0012601	
00028		DEFECTIVE	=	0012601	
00029		DEFECTIVE		0072900	
00030		DEFECTIVE	-	0072900	
00031	w w			/DOVRRNHTH	020501
00032	w w	C 101 /OMC	/CNCRNHSO	/DOVRRNHTH	020501

COMMAND CABLE BULK ASSIGNMENT AND SCAN (CBLS) /FOR
TERM A EPSMNHBH TERM Z CNCRNHSO CABLE 7748 SUBPATH CT0S0F
FROM UNIT 00001 LAST UNIT 00004 QTY SPARE 0000 TOT QTY 00004
CMPL DATE 03 20 96 INV STAT IE 2-W SPARES 0000 1-W SPARES 0000
FAC DETAIL LGS FAC USE G FAC GROUP COMP ID A
NO OF SPRS NO OF WIRES SHLD/DIR CKT/CLO SCAN N

ASGT DATA: ALT/PRI DR CLASS MISUSE MW TERMN: FRAMES SEQ NBR

		_ • •		IC HAIL	020	·Dic	
			CTIVIT	_			
UNIT 1	F T RS1	'N (CUR PN	DDF	CKTID	/CLO	DUE DATE
00001	DEF J	J	OPEN	I IN SH	EATH		
00002	J J	C	MTCE	FIBER		121500	
00003	W	W	C 101	/OMC	/CNCRNHSO	/DOVRNHTH	020501
00004	W	W	C 101	/OMC	/CNCRNHSO	/DOVRNHTH	020501
00005	W	W	Y C 301	/T6X2	P/CNCRNHSO	/MNCHNHCO	030293
00006	W	W	Y C 301	/T6X2	P/CNCRNHSO	MNCHNHCO	030293
00007	W	W	Y C 301	/T6X2	P /DOVRNHTH	I /MNCHNHCO	022493
00008	W	W	Y C 301	/T6X2	P/DOVRNHTE	I /MNCHNHCO	022493
00009	DEF S	\$ \$					
00010	J		MTCE F	IBER			
00011	W	W	C 1001	/OC48	/CNCRNHSO	/DOVRNHTH	021497
00012	W	\mathbf{W}	C 1001	/OC48	/CNCRNHSO	/DOVRNHTH	021497
00013	W	W	C 1001	/OC12	/CNCRNHSO	/NWODNHYA	072397
00014	W	\mathbf{W}	C 1001	/OC12	/CNCRNHSO	/NWODNHYA	072397
00015	J	J	PENDI	NG_DV	VDMNH01		
00016	J	J	PENDI	NG DW	/DMNH01		
00017	W	W	C 1002	/OC12	/CNCRNHSO	/NWODNHYA	112197
00018	W	W	C 1002	/OC12	/CNCRNHSO	/NWODNHYA	112197
00019	J	J	PENDI	NG NHI	NOQD		
00020	J	J	PENDI	<u>NG</u> NHI	NOQD		
00021	W	W	C 1005	/OC12	/CNCRNHSO	/NWODNHYA	090999
00022	W	W	C 1005	/OC12	/CNCRNHSO	/NWODNHYA	090999
00023	\mathbf{w}	W	C 3001	/OC48	/CNCRNHSO	/ROCHNHWE	051701
00024	W	W	C 3001	/OC48	/CNCRNHSO	/ROCHNHWE	051701
00025	W	W	C 1001	/OC12	/CNCRNHSO	/EPSMNHBH	032200
00026	W	W	C 1001	/OC12	/CNCRNHSO	/EPSMNHBH	032200
00027	W	W	C 3002	/OC48	/CNCRNHSO	/DOVRNHTH	020400
00028	W	W	C 3002	/OC48	/CNCRNHSO	/DOVRNHTH	020400


COMMAND CABLE BULK ASSIGNMENT AND SCAN (CBLS) /FOR
TERM A CANDNHDE TERM Z MNCHNHCO CABLE 8076 SUBPATH CT000F
FROM UNIT 00003 LAST UNIT 00006 QTY SPARE 0001 TOT QTY 0004
CMPL DATE 11 24 95 INV STAT IE 2-W SPARES 0000 I-W SPARES 0000
FAC DETAIL LGS FAC USE G FAC GROUP COMP ID A
NO OF SPRS NO OF WIRES SHLD/DIR CKT/CLO SCAN N

ASGT DATA: ALT/PRI DR CLASS MISUSE MWW
TERMN: FRAMES SEQ NBR

30.	ועם	42G1	ACII	AIII
NIT	FT	RSTN	CUR	PND

00003 W W C 1001 /OC12 /DRFDNHCC /MNCEHNHCO 032200 00004 W W C 1001 /OC12 /DRFDNHCC /MNCEHNHCO 032200 00005 \$ A SIS009366001 0122102 00006 \$ \$ C 1001 /OC12P /MNCHNHCO /RYMNNHFL 060597 00007 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00008 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00009 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00014 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00010 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 020501 00019 W W C 101 /OMC /EXTRNHCE /MNCHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHNHCO 020501 00022	UNIT	FT RSTN C	CUR PND D F	CKTII)/CLO	DUE DATE
00005 \$ A SIS009366001 0122102 00006 \$ \$ C 1001 /OC12P /MNCHNHCO /RYMNNHFL 060597 00007 W W C 1002 /OC48 /EXTRNHCE /MNCHHNHCO 021497 00008 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00009 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 020498 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 020501 00022 J J PENDING DWDMNH01 021296	00003	w w	C 1001/OC12	/DRFDNHCC	/MNCEHNHCO	032200
00006 \$ \$ C 1001 /OC12P /MNCHNHCO /RYMNNHFL 060597 00007 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00008 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00009 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNHFL 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00017 J J PENDING NHNOJH 020498 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 0202501 00022 J J PENDING DWDMNH01 021296	00004	$\mathbf{w} \cdot \mathbf{w}$	C 1001 /OC12	/DRFDNHCC	/MNCEHNHCO	032200
00007 W W C 1002 /OC48 /EXTRNHCE /MNCHINHCO 021497 00008 W W C 1002 /OC48 /EXTRNHCE /MNCHINHCO 021497 00009 W W C 1001 /OC48 /EXTRNHCE /MNCHINHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHINHCO 060597 00011 W W C 1001 /OC12 /MNCHINHCO /RYMMINHFL 060597 00012 W W C 1001 /OC12 /MNCHINHCO /RYMMINHFL 060597 00013 W W C 1001 /OC12P /MNCHINHCO /RYMMINHFI 060597 00014 W W C 1001 /OC12P /MNCHINHCO /RYMMINHFI 060597 00015 W W C 1001 /OC48 /MNCHINHCO /RYMMINHFL 020498 00016 W W C 1001 /OC48 /MNCHINHCO /RYMMINHFL 020498 00017 J J PENDING INHOJH 020498 00019 W W C 101 /OMC /EXTRNHCE /MNCHINHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHINHCO 020501 00021 J J PENDING DWDMINHO1 020501 00022 J J PENDING DWDMINHO1 021296	00005	\$ A	SIS009366001		0122102	
00008 W W C 1002 /OC48 /EXTRNHCE /MNCHNHCO 021497 00009 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNHFI 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNHFI 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00017 J J PENDING NHNOJH 020498 00018 J J PENDING NHNOJH 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 020501 00022 J J PENDING DWDMNH01 021296	00006	\$ \$ C	1001/OC12P/	MNCHNHCO	/RYMNNNHFL	060597
00009 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 020498 00018 J J PENDING NHNOJH 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 020501 00022 J J PENDING DWDMNH01 021296	00007	w w	C 1002 /OC48	/EXTRNHCE	/MNCHHNHCO	021497
00010 W W C 1001 /OC48 /EXTRNHCE /MNCHNHCO 060597 00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFL 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 00018 00018 J J PENDING NHNOJH 00019 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /I 021296	00008	$\mathbf{w} \ \mathbf{w}$	C 1002 /OC48	/EXTRNHCE	/MNCHNHCO	021497
00011 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFI 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFI 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDINGNHNOJH 00018 00018 J J PENDINGNHNOJH 00019 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 00023 W W S 74/LMDA/72578 /NE /1 021296	00009	$\mathbf{w} \ \mathbf{w}$	C 1001 /OC48	/EXTRNHCE	/MNCEHNHCO	060597
00012 W W C 1001 /OC12 /MNCHNHCO /RYMMNNHFL 060597 00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFI 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFI 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 00018 00018 J J PENDING NHNOJH 00019 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00010	$\mathbf{w} \cdot \mathbf{w}$	C 1001 /OC48	/EXTRNHCE	/MNCFHNHCO	060597
00013 W W C 1001 /OC12P /MNCHNHCO /RYMMNHFI 060597 00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNHFI 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNHFL 020498 00017 J J PENDING NHNOJH 00018 00018 J J PENDING NHNOJH 00019 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00011	w w	C 1001 /OC12	/MNCHNHCC	/RYMMNNHFI	. 060597
00014 W W C 1001 /OC12P /MNCHNHCO /RYMMNNHFI 060597 00015 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00016 W W C 1001 /OC48 /MNCHNHCO /RYMMNNHFL 020498 00017 J J PENDING NHNOJH 020498 00018 J J PENDING NHNOJH 00019 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00012	$\mathbf{w} \cdot \mathbf{w}$	C 1001 /OC12	/MNCHNHCC	/RYMMNNHFL	. 060597
00015 W W C 1001 / OC48 / MNCHNHCO / RYMMNNHFL 020498 00016 W W C 1001 / OC48 / MNCHNHCO / RYMMNNHFL 020498 00017 J J PENDING NHNOJH 00018 00018 J J PENDING NHNOJH 00019 00019 W W C 101 / OMC / EXTRNHCE / MNCHHNHCO 020501 00020 W W C 101 / OMC / EXTRNHCE / MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 / NE / I 021296	00013	w w	C 1001 /OC12	P/MNCHNHC	O /RYMMNNHF.	060597
00016 W W C 1001 / OC48 / MNCHNHCO / RYMMNHFL 020498 00017 J J PENDING NHNOJH 00018 00018 J J PENDING NHNOJH 00019 00019 W W C 101 / OMC / EXTRNHCE / MNCHHNHCO 020501 00020 W W C 101 / OMC / EXTRNHCE / MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 / NE / I 021296	00014	$\mathbf{w} \ \mathbf{w}$	C 1001 /OC12	P/MNCHNHC	O /RYMMNNHF.	060597
00017 J J PENDING_NHNOJH 00018 J J PENDING_NHNOJH 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING_DWDMNH01 00022 J J PENDING_DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00015	\mathbf{w}	C 1001 /OC48	MNCHNHCC	/RYMMNNHFL	. 020498
00018 J J PENDING NHNOJH 00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /I 021296	00016	W W	C 1001 /OC48	/MNCHNHCC	/RYMMNNHFL	. 020498
00019 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /I 021296	00017	J J	PENDING_NI	ĪNОЛН		
00020 W W C 101 /OMC /EXTRNHCE /MNCHHNHCO 020501 00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /I 021296	00018	JЈ	PENDING NE	INOJH		
00021 J J PENDING DWDMNH01 00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00019	w w	C 101 /OMC	/EXTRNHCE	/MNCHHNHCO	020501
00022 J J PENDING DWDMNH01 00023 W W S 74/LMDA/72578 /NE /1 021296	00020	w w	C 101 /OMC	/EXTRNHCE	/MNCHHNHCO	020501
00023 W W S 74/LMDA/72578 /NE /1 021296	00021	JJ	PENDING D	WDMNH01		
	00022	1 1	PENDING D	WDMNH01		
00024 W W S 74/LMDA/72578 /NE /1 021296	00023	w w	S 74/LMDA/7	2578 /NE /1	02129	96
	00024	w w	S 74/LMDA/7	2578 /NE /1	02129	96

Dover-Manchester Fiber Blockage





Dark Fiber Inquiry Form

			•			
CLEC Section (E-mail form to une.dfi@veriz	on.com)				
CLEC Name	CTC Communications	Date Sent	8/27/01			
CLEC Contact	Craig Cucchiara	Tel Number	781.522.866	57	-	
Street	220 Bear Hill Rd	Fax Number	781.522.879	_		
Floor/Room						
City & State	Waltham MA 02451	E-Mail	ccucchiara@c	ctcnet.com	<u> </u>	
Location Inform	ation Section					
Primary Location	VZ Central Office		POI CLLI	BURLV	TMA	
Street	266 Main Street		_		·	
City & State	Burlington VT 05401		LATA	124		
Additional Inform	ation					
Secondary Locat	ion CTC Central Office		XPOI CLLI	WLST\	/T07	
Street	1193 South Brownell Rd		_			
City & State	Williston VT 05495		NPA-NXX	802-65	2	
Additional Inform	ation this is a CTC POP with VZ fibe	er entrance facilities				
Service Delivery Date Received SDE	Engineer (SDE) Information Sectio 08/27/01 Date For Michelle Lawrence	rward to Engineering	08/28/01 617 743-674	18		
Street	125 High St., RM 1256	FAX Number	617 261-646	61		
City & State	Boston, MA 02110	E-Mail	michelle.b.lawrence@verizon.com			
Date Reply To Ci						
Engineering Into	ormation Section 8/28/01	Reply To SDE By	09/13/01			
Engineer	Harv Tasch	Reply Date	9/5/01		· · · · · · · · · · · · · · · · · · ·	
Street	140 West Street	Tel Number		·		
City & State	New York, NY, 10007	FAX Number				
Organization	IOF Planning	E-Mail			· · · · · · · · · · · · · · · · · · ·	
Comments	NO DIRECT ROUTE BURLVTMA-				<u>, , </u>	
	NO FIBERS		.			
Fibers Available	To Meet Request (Y/N) N	If NO	, Number Of	Fiber Pai i	rs <u>##</u>	
To Be Complete	d By Engineering:					
					Work Activity	
Description				Miles	(Hours)	
Mileage for Availa	able Dark Fiber				and the second of the second	

Inquiry Number:

CTCCBURLWLST8-27-1ML

NOTICE: This does not constitute an order for Dark Fiber. To order available Dark Fiber, the CLEC must follow-up with an ASR delivered to Verizon as soon as possible following notification of availability. Until an ASR is received by Verizon, Dark Fiber remains in inventory and available for Verizon use and/or to meet other CLEC requests. Verizon does not reserve Dark Fiber.

Information contained in this response is based solely upon a review of Verizon's cable records. Verizon makes no representation or warranty regarding the accuracy or completeness of such records. The CLEC has the option of requesting Verizon perform a field survey at the CLEC's expense to verify Dark Fiber availability. Should the CLEC decline the field survey and place an order for Dark Fiber based solely on the information contained in this response, the CLEC assumes all risks of relying on such records.

Planning Engineer Hours - TM1DA (North Only)

Design Engineer Hours - TM1DB (North Only)

0.5

Before the FEDERAL COMMUNICATIONS COMMISSION Washington, D.C. 20554

In the Matter of)	
Review of the Section 251 Unbundling Obligations of Incumbent Local Exchange Carriers)))	CC Docket No. 01-338
Implementation of the Local Competition Provisions of the Telecommunications Act of 1996)))	CC Docket No. 96-98
Deployment of Wireline Services Offering Advanced Telecommunications Capability)))	CC Docket No. 98-147

DECLARATION OF PATRICIA HOGUE

The undersigned, being duly sworn on oath, does say and depose as follows:

- 1. My name is Patricia Hogue. Presently, I am employed as a consultant for El Paso Global Networks ("EPN"), and have served as its lead negotiator in all negotiations with incumbent local exchange carriers ("ILECs") for matters relating to interconnection and access to unbundled network elements. I also supervise other EPN personnel that participate in the negotiations process.
- 2. I have over 32 years of telecommunications experience; the last one and one-half years with EPN. Prior to joining EPN, I was employed in a variety of positions at SBC Communications. My positions at SBC ranged from serving as its Director of Negotiations with CLECs to splicing dark fiber in manholes beneath the streets of Dallas, Texas. In between, I served as: a negotiator on interconnection agreements with CLECs; a senior account executive serving the needs of SBC's large customers, a design engineer

responsible for designing SONET deployments and day-to-day deployment of facilities in a major metropolitan wire center; a customer service representative; and, of course, as a cable splicing technician, where I spliced fiber optic cable throughout North Texas, and oversaw the use of the JMOS database. In short, in my 30-plus years of experience in the industry, I have worked on a vast array of telecommunications related matters.

- 3. EPN's prior experience with obtaining dark fiber from SBC in Texas illustrates that if permitted by the Commission, SBC's refusal to splice dark fiber would exclude a significant percentage of SBC's dark fiber facilities from unbundling. Specifically, of the actual dark fiber service orders submitted by EPN to SBC since 1999, a significant percentage of the dark fiber loops required splicing at least one point in the path of the fiber to provide EPN with a continuous fiber loop. If SBC had not been required to splice dark fiber loops for EPN, then the percentage of dark fiber loops ordered by EPN that would have been unavailable to EPN in the following major Texas markets is as follows: Austin 47%, Dallas 72%, Fort Worth 55%, Houston 60%, San Antonio 66%. In fact, in testimony filed in Texas in docket 25188, Mr. Chad Townes, Director for SBC, outlines the fact that SBC regularly leaves fibers stranded and unspliced, ready to be called into service as customers request high bandwidth services. These fibers are "dead count" that can be readily called into service, yet the ILECs want the deployed fiber to be artificially excluded from its unbundling obligation.
- 4. Termination of fiber frequently requires some splicing. In particular, ILECs routinely perform a fusion splice to connect a fiber pigtail to a fiber cable in a splice tray within the central office in order to terminate the fiber cable at a fiber distribution panel. This type of splicing is routinely performed in a controlled environment by ILECs to serve their

own customers and should be performed to terminate dark fiber in order to provide dark fiber loops and transport to CLECs. That such splicing does not implicate any network reliability issues as evidenced by the fact that ILECs routinely perform such splicing for themselves. Unless ILECs are required to perform such splicing for CLECs in order to terminate dark fiber, ILECs can deliberately leave dark fiber that has been pulled within or lies just outside the central office unspliced and unterminated in order to reduce the dark fiber inventory that is available to CLECs.

Parity access to ILEC dark fiber information is especially crucial because ILEC responses to CLEC requests for dark fiber have often proved to be erroneous. As a result, CLECs must have parity access to ILEC preordering and ordering information regarding dark fiber network elements that is up-to-date in order to independently determine the veracity of ILEC representations that dark fiber UNEs are unavailable. For example, SBC has routinely misstated the availability of dark fiber to EPN or withheld information on such availability choosing to play a cat and mouse game during the facility check process. SBC would not divulge the existence of dark fiber unless EPN guessed at the exact location of the demarcation point, for instance, in a multi-tenant building. SBC is not forthright with any information during the facility check process, choosing rather to look for opportunities to deny the use of UNEs to CLECs. In fact, the last twenty times that EPN checked SBC's outside plant records to determine the accuracy of SBC's representations that dark fiber was unavailable, EPN determined that contrary to SBC's representations dark fiber was in fact available but SBC deemed it not necessary to supply such fiber as an UNE to EPN by creating artificial barriers and new rules at every turn. EPN engineers have also personally inspected customer premises and found dark

- fiber present, notwithstanding SBC's representations in dark fiber facility check responses that dark fiber was unavailable.
- 6. SBC has consistently provided inaccurate information to EPN regarding the availability of dark fiber UNEs which underscores the need for parity access to information so that CLECs can make an independent judgement regarding the availability of dark fiber UNEs. In fact, in twenty out of twenty instances in which EPN went to the expense of reviewing SBC's records after SBC advised EPN that no dark fiber was available, EPN's record review revealed that dark fiber was in fact available.
- 7. SBC's Design Work Orders are often the most up-to-date source of information on recently completed fiber installations and fiber installations that are in progress and near completion. Despite the Texas Public Utilities Commission's clear direction that SBC provide information regarding recently completed and in progress fiber installations, SBC often denies access to Design Work Orders ostensibly because SBC does not consider the construction complete until the data is posted in the Plant Layout Records, even if SBC has already been providing service to customers on the installed fiber for months or even over a year. Additionally, SBC regularly included route and path information, such as the location of intermediate offices and cabling numbers, on its facility check responses until March, 2001. Recently, however, SBC has apparently instructed its Local Service Center personnel to affirmatively delete such route and path information before providing the response to the CLEC.
- 8. While SWBT has refused to divulge its fiber standards for retail services to EPN, when any carrier splices or terminates fibers so that it may light a fiber for its own use, it would normally test for dB loss using ANSI 568-B or a comparable testing procedure. Both

testing for signal loss and reflection are standard procedures that I did for each and every fiber splicing job almost twenty years ago as a fiber optic cable splicing technician for Southwestern Bell.

9. Internally, SBC treats dark fiber as deployed fiber, regardless of whether the facility would need to be spliced in order to be called into service. For example, these fibers are recorded as deployed on SBC's Plant Layout Records database, which is used to identify facilities that can easily be called into service. Also, these dark fiber facilities are recorded as deployed in SBC's Job Management Operating System, which is tied to the property and tax databases SBC uses to identify deployed assets.

I hereby declare under penalty of perjury that the contents of the foregoing Declaration are true and correct to my personal knowledge. Executed on April 4, 2002.

Patricia Hogue

400397v1